

## Ferris<sup>®</sup> Sticky Wax

## Description

Ferris Sticky Wax is a quick-setting adhesive which creates a rigid bond between two wax surfaces. It is ideal for attaching wax patterns to the central sprue rod. Ferris Sticky Wax will not hinder melt-out, leaves no residue, and is ideal for both large and small parts.

## **Physical Properties**

Color	Yellow
Ring & Ball Softening Point (°F)	149-161
Congealing Temperature (°F)	143-155
Recommended Application Temperature (°F)	225-275

## **Ordering Information**

Available in Beads or Sticks (1/4" diameter x 5" long).

SKU	Description	UM	Net Weight
119610	Sticky Wax Yellow <sup>1</sup> / <sub>4</sub> D x 5 L	box	0.2 lbs
118274	Bead Sticky Wax Yellow 1# Container	lb	1 lb
118273	Bead Sticky Wax Yellow 50lb Bulk	box	50 lbs

The user shall determine the suitability of this product for their application and assumes all risks and liabilities associated with the use of this product. The exclusive remedy for all proven claims is replacement of our materials only and in no event shall Freeman Mfg. & Supply Co. be liable for special, incidental, or consequential claims.

READ SAFETY DATA SHEETS AND PRODUCT LABELS BEFORE USING PRODUCT

Ferris is a registered trademark of Freeman Manufacturing & Supply Company.